

Firmware 3.31P15



New Release and Update Information

Firmware Core: 3.31P15

Compatible RAIDWatch version: 1.53

Software updates are available at <ftp.infortrend.com.tw/RAIDWatch/1.53>

1. Overview

No new features added to this revision. This revision aims to solve some known issues.

2. Applicable Products

Firmware 3.31P15 is applicable to the following subsystems:

Models	Corresponding Binary
EonStor A16F-R1A2	TBD
EonStor A16U-S1A2-9930	TBD

3. List of Problems Fixed

Sub-menu missing

The "Redundant Controller" sub-menu is missing.

Location of the sub-menu:

"Main Menu" -> "View and Edit Peripheral Devices" -> "Set Peripheral Device Entry" -> "Redundant Controller" -> "Enable/Disable redundant controller function"