

# Firmware 3.3106



## New Release and Update Information

Firmware Core: 3.3106

Compatible RAIDWatch version: 1.54

Software updates are available at [ftp.infortrend.com.tw/RAIDWatch/1.54](http://ftp.infortrend.com.tw/RAIDWatch/1.54)

### 1. Overview

No new features added to this revision. This revision aims to solve some known issues.

### 2. Applicable Products

Firmware 3.3106 is applicable to the following controller/subsystems:

Models	Version previously applied
<i>FC RAID models</i>	
EonStor F12F-G2A2	3.31K13
EonStor F16F-S2A2	3.31J12
EonRAID 2510FS-4D/6D	3.31M11
EonRAID 2510FS-4S/6S	3.31M11
EonRAID 2510FS-4RH/6RH	3.31M11
<i>SCSI RAID models</i>	
SentinelRAID 150F	3.25O
SentinelRAID 1500F	3.27D1
SentinelRAID 2500F	3.25O
EonStor U12U-G3A3	3.31K13
EonStor U16U-G3A3-4	3.31I18
EonStor U16U-G3A3-6	3.31I18

### 3. List of Problems Fixed

- 1) **Incorrect terminal information**  
Incorrect display of the "Regenerate Parity Percentage" on terminal screen.
- 2) **Controller abnormal reset**  
Controller abnormal reset when trying to add FC host port entries (WWN or nick name) to the "Host ID/WWN list".
- 3) **LCD malfunctioning**  
LCD sub-menus not functional when adding new drives to existing logical drives.